

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Mark E, 10' Body
	List Truck Type Box Fits	Single Axle with 84" CA
	Box Style	Cross Memberless
	Width & Length of Box	10' long x 96" width
	Side Panel Description	24"-10 gauge high sides, grade 50, 65000 PSI, 1 piece contoured construction with formed horizontal weld on side brace, Flat top dirt shedding top rail and side braces, 2" board pockets
	Front Panel Description	10 gauge, grade 50, 65000 PSI steel
	Floor Description	1- piece 3/16" HSLA grade 50, 65000 PSI steel, Integral 5" floor to side radius
	Corner Post Description	Front contoured 10 gauge, grade 50, 65000 PSI steel Rear 4 3/4" x 12", 7 gauge full depth, tied to 8" steel flush rear apron.
	Under Structure Description	8" structural steel "I" beams (UB hoist)
	Tailgate Description	32" -10 gauge, grade 50, 65000 PSI steel, with one horizontal brace
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting, package, rubber grommets with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	No
	Is Box Painted?	No
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 3,933
	TOTAL PRICE:	\$ 10,940

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
Box Options		
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Model Mark E Body	\$ 10,794
1.6	Deduct front corner post (No Charge)	\$ -
1.7	Mark "E" Asphalt style, slopes rear end and tailgate ILO Std	\$ 294
1.8	Heated Body, (Floor/Rub rail) req 12V regen signal, No UB Hoist (MKE-TA) (Uses 1/4 Mild Steel Formed Longsills ILO Ibeam) (upfitter supplied diverter) (\$ per foot of body length)	\$ 177
1.9	Install heated body portion	\$ -
1.50	3/16" AR400 floor ILO Std (Mild Steel)	\$ 1,017
1.51	1/4" AR400 floor ILO Std (Mild Steel)	\$ 1,554
1.52	30"-10 gauge sides/ends ILO Std 24" sides (Mild Steel)	\$ 101
1.53	24"-7 gauge sides/ends ILO Std 24" sides (Mild Steel)	\$ 422
1.54	30"-7 gauge sides/ends ILO Std 24" sides (Mild Steel)	\$ 563
1.55	24"-3/16" AR400 sides/ends ILO Std 24" sides (Mild Steel) (7GA TR/RR)	\$ 3,051
1.56	30"-3/16" AR400 sides/ends ILO Std 24" sides (Mild Steel) (7GA TR/RR)	\$ 3,392
1.57	24"-10 gauge sides/ends ILO Std 24" sides (SS201)	\$ 8,003
1.58	30"-10 gauge sides/ends ILO Std 24" sides (SS201)	\$ 8,398
1.59	24"-7 gauge sides/ends ILO Std 24" sides (SS201)	\$ 9,813
1.60	30"-7 gauge sides/ends ILO Std 24" sides (SS201)	\$ 10,372
1.61	Flush sides and tailgate (No Charge Option)	\$ -
1.64	Walk rail, 2" SURE STEP full length (SS201) Both Sides	\$ 510
1.65	8" Channel Boxed Bolt-in Side Boards (Mild Steel)	\$ 1,673
1.66	8" Channel Boxed Bolt-in Side Boards (201 Stainless Steel)	\$ 2,072
1.67	1-1/2" wood side boards	\$ 628
1.68	1-1/2" x 7-1/2" 10' Fiberforce composite side boards	\$ 887
SEE "1.0 Box (Options) Page" for additional accessories & options		
Cost per loaded mile for pickup and or delivery of vehicle (if applicable):		\$ 7
Delivery Starting Point City, State, & Zip:		
Bloomington, MN 55420		
Body Shop Rate		\$ 165
Mechanic Shop Rate		\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Mark E, 11' Body
	List Truck Type Box Fits	Single Axle with 96" CA
	Box Style	Cross Memberless
	Width & Length of Box	11' long x 96" width
	Side Panel Description	24"-10 gauge high sides, grade 50, 65000 PSI, 1 piece contoured construction with formed horizontal weld on side brace, Flat top dirt shedding top rail and side braces, 2" board pockets
	Front Panel Description	10 gauge, grade 50, 65000 PSI steel
	Floor Description	1- piece 3/16" HSLA grade 50, 65000 PSI steel, Integral 5" floor to side radius
	Corner Post Description	Front contoured 10 gauge, grade 50, 65000 PSI steel Rear 4 3/4" x 12", 7 gauge full depth, tied to 8" steel flush rear apron.
	Under Structure Description	8" structural steel "I" beams (UB hoist)
	Tailgate Description	32" -10 gauge, grade 50, 65000 PSI steel, with one horizontal brace
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting, package, rubber grommeted with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u> ___
	Is Box Painted?	Yes ___ or No <u>X</u> ___
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,002
	TOTAL PRICE:	\$ 11,963

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Model Mark E Body	\$ 10,794
1.6	Deduct front corner post (No Charge)	\$ -
1.7	Mark "E" Asphalt style, slopes rear end and tailgate ILO Std	\$ 294
1.8	Heated Body, (Floor/Rub rail) req 12V regen signal, No UB Hoist (MKE-TA) (Uses 1/4 Mild Steel Formed Longsills ILO Ibeam) (upfitter supplied diverter) (\$ per foot of body length)	\$ 177
1.9	Install heated body portion	\$ 6,223
1.50	3/16" AR400 floor ILO Std (Mild Steel)	\$ 1,210
1.51	1/4" AR400 floor ILO Std (Mild Steel)	\$ 1,854
1.52	30"-10 gauge sides/ends ILO Std 24" sides (Mild Steel)	\$ 115
1.53	24"-7 gauge sides/ends ILO Std 24" sides (Mild Steel)	\$ 465
1.54	30"-7 gauge sides/ends ILO Std 24" sides (Mild Steel)	\$ 622
1.55	24"-3/16" AR400 sides/ends ILO Std 24" sides (Mild Steel) (7GA TR/RR)	\$ 3,290
1.56	30"-3/16" AR400 sides/ends ILO Std 24" sides (Mild Steel) (7GA TR/RR)	\$ 3,677
1.57	24"-10 gauge sides/ends ILO Std 24" sides (SS201)	\$ 7,641
1.58	30"-10 gauge sides/ends ILO Std 24" sides (SS201)	\$ 7,805
1.59	24"-7 gauge sides/ends ILO Std 24" sides (SS201)	\$ 9,269
1.60	30"-7 gauge sides/ends ILO Std 24" sides (SS201)	\$ 9,871
1.61	Flush sides and tailgate (No Charge Option)	\$ -
1.64	Walk rail, 2" SURE STEP full length (SS201) Both Sides	\$ 563
1.65	8" Channel Boxed Bolt-in Side Boards (Mild Steel)	\$ 1,729
1.66	8" Channel Boxed Bolt-in Side Boards (201 Stainless Steel)	\$ 2,149
1.67	1-1/2" wood side boards	\$ 617
1.68	1-1/2" x 7-1/2" 10' Fiberforce composite side boards	\$ 770

SEE "1.0 Box (Options) Page" for additional accessories & options

	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Mark E, 12' Body
	List Truck Type Box Fits	Single Axle with 108" CA
	Box Style	Cross Memberless
	Width & Length of Box	12' long x 96" width
	Side Panel Description	24"-10 gauge high sides, grade 50, 65000 PSI, 1 piece contoured construction with formed horizontal weld on side brace, Flat top dirt shedding top rail and side braces, 2" board pockets
	Front Panel Description	10 gauge, grade 50, 65000 PSI steel
	Floor Description	1- piece 3/16" HSLA grade 50, 65000 PSI steel, Integral 5" floor to side radius
	Corner Post Description	Front contoured 10 gauge, grade 50, 65000 PSI steel Rear 4 3/4" x 12", 7 gauge full depth, tied to 8" steel flush rear apron.
	Under Structure Description	8" structural steel "I" beams (UB hoist)
	Tailgate Description	32" -10 gauge, grade 50, 65000 PSI steel, with one horizontal brace
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting, package, rubber grommets with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,070
	TOTAL PRICE:	\$ 12,179

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
Box Options		
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Model Mark E Body	\$ 10,794
1.6	Deduct front corner post (No Charge)	\$ -
1.7	Mark "E" Asphalt style, slopes rear end and tailgate ILO Std	\$ 294
1.8	Heated Body, (Floor/Rub rail) req 12V regen signal, No UB Hoist (MKE-TA) (Uses 1/4 Mild Steel Formed Longsills ILO Ibeam) (upfitter supplied diverter) (\$ per foot of body length)	\$ 177
1.9	Install heated body portion	\$ 6,223
1.50	3/16" AR400 floor ILO Std (Mild Steel)	\$ 1,325
1.51	1/4" AR400 floor ILO Std (Mild Steel)	\$ 2,030
1.52	30"-10 gauge sides ILO Std 24" sides (Mild Steel)	\$ 124
1.53	24"-7 gauge sides ILO Std 24" sides (Mild Steel)	\$ 486
1.54	30"-7 gauge sides ILO Std 24" sides (Mild Steel)	\$ 655
1.55	24"-3/16" AR400 sides ILO Std 24" sides (Mild Steel) (7GA TR/RR)	\$ 3,373
1.56	30"-3/16" AR400 sides ILO Std 24" sides (Mild Steel) (7GA TR/RR)	\$ 3,786
1.57	24"-10 gauge sides ILO Std 24" sides (SS201)	\$ 7,606
1.58	30"-10 gauge sides ILO Std 24" sides (SS201)	\$ 8,060
1.59	24"-7 gauge sides ILO Std 24" sides (SS201)	\$ 9,577
1.60	30"-7 gauge sides ILO Std 24" sides (SS201)	\$ 10,221
1.61	Flush sides and tailgate (No Charge Option)	\$ -
1.64	Walk rail, 2" SURE STEP full length (SS201) Both Sides	\$ 613
1.65	8" Channel Boxed Bolt-in Side Boards (Mild Steel)	\$ 1,782
1.66	8" Channel Boxed Bolt-in Side Boards (201 Stainless Steel)	\$ 2,227
1.67	1-1/2" wood side boards	\$ 617
1.68	1-1/2" x 7-1/2" 10' Fiberforce composite side boards	\$ 770
SEE "1.0 Box (Options) Page" for additional accessories & options		
	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mqxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Mark E, 13' Body
	List Truck Type Box Fits	Tandem Axle with 108" CT
	Box Style	Cross Memberless
	Width & Length of Box	13' long x 96" width
	Side Panel Description	36"-10 gauge high sides, grade 50, 65000 PSI, 1 piece contoured construction with formed horizontal weld on side brace, Flat top dirt shedding top rail and side braces, 2" board pockets
	Front Panel Description	60"-10 gauge, grade 50, 65000 PSI steel
	Floor Description	1- piece 3/16" HSLA grade 50, 65000 PSI steel, Integral 5" floor to side radius
	Corner Post Description	Front contoured 10 gauge, grade 50, 65000 PSI steel Rear 4 3/4" x 12", 7 gauge full depth, tied to 8" steel flush rear apron.
	Under Structure Description	8" structural steel "I" beams (Tele hoist)
	Tailgate Description	44" -10 gauge, grade 50, 65000 PSI steel, with one horizontal brace
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting, package, rubber grommets with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,207
	TOTAL PRICE:	\$ 13,339

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
Box Options		
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Model Mark E Body	\$ 10,794
1.6	Deduct front corner post (No Charge)	\$ -
1.7	Mark "E" Asphalt style, slopes rear end and tailgate ILO Std	\$ 294
1.8	Heated Body, (Floor/Rub rail) req 12V regen signal, No UB Hoist (MKE-TA) (Uses 1/4 Mild Steel Formed Longsills ILO Ibeam) (upfitter supplied diverter) (\$ per foot of body length)	\$ 177
1.9	Install heated body portion	\$ 6,223
1.50	3/16" AR400 floor ILO Std (Mild Steel)	\$ 1,493
1.51	1/4" AR400 floor ILO Std (Mild Steel)	\$ 2,305
1.52	44"-10 gauge sides ILO Std 36" sides (Mild Steel)	\$ 339
1.53	36"-7 gauge sides ILO Std 36" sides (Mild Steel)	\$ 605
1.54	44"-7 gauge sides ILO Std 36" sides (Mild Steel) (7GA TR)	\$ 1,094
1.55	36"-3/16" AR400 sides ILO Std 36" sides (Mild Steel) (7GA TR/RR)	\$ 4,274
1.56	44"-3/16" AR400 sides ILO Std 36" sides (Mild Steel) (7GA TR/RR)	\$ 4,800
1.57	36"-10 gauge sides ILO Std 36" sides (SS201)	\$ 9,063
1.58	44"-10 gauge sides ILO Std 36" sides (SS201)	\$ 10,294
1.59	36"-7 gauge sides ILO Std 36" sides (SS201)	\$ 11,552
1.60	44"-7 gauge sides ILO Std 36" sides (SS201) (7GA TR/RR)	\$ 13,320
1.61	Flush sides and tailgate (No Charge Option)	\$ -
1.62	Double horizontal side brace ILO Std (Mild Steel)	\$ 299
1.63	Double horizontal side brace ILO Std (SS201)	\$ 728
1.64	Triple horizontal side brace ILO Std (Mild Steel) (44" SIDE BODIES ONLY)	\$ 598
1.65	Triple horizontal side brace ILO Std (SS201) (44" SIDE BODIES ONLY)	\$ 1,458
1.68	Walk rail, 2" SURE STEP full length (SS201) Both Sides	\$ 673
1.69	3/4" Round tarp rail both sides (Mild Steel) On side brace	\$ 303
1.70	3/4" Round tarp rail both sides (SS304) On side brace	\$ 505
1.71	8" Channel Boxed Bolt-in Side Boards (Mild Steel)	\$ 1,837
1.72	8" Channel Boxed Bolt-in Side Boards (201 Stainless Steel)	\$ 2,304
1.73	1-1/2" wood side boards	\$ 620
1.74	1-1/2" x 7-1/2" 13' Fiberforce composite side boards	\$ 791

SEE "1.0 Box (Options) Page" for additional accessories & options

SEE "1.0 Box (Options) Page" for additional accessories & options		
	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Mark E, 14' Body
	List Truck Type Box Fits	Tandem Axle with 120" CT
	Box Style	Cross Memberless
	Width & Length of Box	14' long x 96" width
	Side Panel Description	36"-10 gauge high sides, grade 50, 65000 PSI, 1 piece contoured construction with formed horizontal weld on side brace, 5" radius corners, dirt shedding top rail and side braces, 2" board pockets
	Front Panel Description	60"-10 gauge, grade 50, 65000 PSI steel
	Floor Description	1- piece 3/16" HSLA grade 50, 65000 PSI steel Integral 5" floor to side radius
	Corner Post Description	Flat top dirt shedding top rail and side braces, 2" board pockets 60"-10 gauge, grade 50, 65000 PSI steel
	Under Structure Description	1- piece 3/16" HSLA grade 50, 65000 PSI steel, Integral 5" floor to side radius
	Tailgate Description	Front contoured 10 gauge, grade 50, 65000 PSI steel
	Hinge Description	Rear 4 3/4" x 12", 7 gauge full depth, tied to 8" steel flush rear apron.
	Description of Peripheral Items (Lights, Access Steps, etc.)	8" structural steel "I" beams (Tele hoist) Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,537
	TOTAL PRICE:	\$ 13,588

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
Box Options		
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Model Mark E Body	\$ 10,794
1.6	Deduct front corner post (No Charge)	\$ -
1.7	Mark "E" Asphalt style, slopes rear end and tailgate ILO Std	\$ 294
1.8	Heated Body, (Floor/Rub rail) req 12V regen signal, No UB Hoist (MKE-TA) (Uses 1/4 Mild Steel Formed Longsills ILO Ibeam) (upfitter supplied diverter) (\$ per foot of body length)	\$ 177
1.9	Install heated body portion	\$ 6,223
1.50	3/16" AR400 floor ILO Std (Mild Steel)	\$ 1,658
1.51	1/4" AR400 floor ILO Std (Mild Steel)	\$ 2,533
1.52	44"-10 gauge sides ILO Std 36" sides (Mild Steel)	\$ 351
1.53	36"-7 gauge sides ILO Std 36" sides (Mild Steel)	\$ 628
1.54	44"-7 gauge sides ILO Std 36" sides (Mild Steel) (7GA TR)	\$ 1,120
1.55	36"-3/16" AR400 sides ILO Std 36" sides (Mild Steel) (7GA TR/RR)	\$ 4,390
1.56	44"-3/16" AR400 sides ILO Std 36" sides (Mild Steel) (7GA TR/RR)	\$ 4,950
1.57	36"-10 gauge sides ILO Std 36" sides (SS201)	\$ 9,327
1.58	44"-10 gauge sides ILO Std 36" sides (SS201)	\$ 10,630
1.59	36"-7 gauge sides ILO Std 36" sides (SS201)	\$ 11,924
1.60	44"-7 gauge sides ILO Std 36" sides (SS201) (7GA TR/RR)	\$ 12,958
1.61	Flush sides and tailgate (No Charge Option)	\$ -
1.62	Double horizontal side brace ILO Std (Mild Steel)	\$ 315
1.63	Double horizontal side brace ILO Std (SS201)	\$ 783
1.64	Triple horizontal side brace ILO Std (Mild Steel) (44" SIDE BODIES ONLY)	\$ 632
1.65	Triple horizontal side brace ILO Std (SS201) (44" SIDE BODIES ONLY)	\$ 1,564
1.68	Walk rail, 2" SURE STEP full length (SS201) Both Sides	\$ 725
1.69	3/4" Round tarp rail both sides (Mild Steel) On side brace	\$ 325
1.70	3/4" Round tarp rail both sides (SS304) On side brace	\$ 544
1.71	8" Channel Boxed Bolt-in Side Boards (Mild Steel)	\$ 1,892
1.72	8" Channel Boxed Bolt-in Side Boards (201 Stainless Steel)	\$ 2,382
1.73	1-1/2" wood side boards	\$ 628
1.74	1-1/2" x 7-1/2" 14' Fiberforce composite side boards	\$ 817
SEE "1.0 Box (Options) Page" for additional accessories & options		
	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mqxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Mark E, 15' Body
	List Truck Type Box Fits	Tandem Axle with 132" CT
	Box Style	Cross Memberless
	Width & Length of Box	15' long x 96" width
	Side Panel Description	36"-10 gauge high sides, grade 50, 65000 PSI, 1 piece contoured construction with formed horizontal weld on side brace, Flat top dirt shedding top rail and side braces, 2" board pockets
	Front Panel Description	60"-10 gauge, grade 50, 65000 PSI steel
	Floor Description	1- piece 3/16" HSLA grade 50, 65000 PSI steel, Integral 5" floor to side radius
	Corner Post Description	Front contoured 10 gauge, grade 50, 65000 PSI steel Rear 4 3/4" x 12", 7 gauge full depth, tied to 8" steel flush rear apron.
	Under Structure Description	8" structural steel "I" beams (Tele hoist)
	Tailgate Description	44" -10 gauge, grade 50, 65000 PSI steel, with one horizontal brace
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting package, rubber grommets with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes or No <input checked="" type="checkbox"/>
	Is Box Painted?	Yes or No <input checked="" type="checkbox"/>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,605
	TOTAL PRICE:	\$ 13,830

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
Box Options		
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Model Mark E Body	\$ 10,794
1.6	Deduct front corner post (No Charge)	\$ -
1.7	Mark "E" Asphalt style, slopes rear end and tailgate ILO Std	\$ 294
1.8	Heated Body, (Floor/Rub rail) req 12V regen signal, No UB Hoist (MKE-TA) (Uses 1/4 Mild Steel Formed Longsills ILO Ibeam) (upfitter supplied diverter) (\$ per foot of body length)	\$ 177
1.9	Install heated body portion	\$ 6,223
1.50	3/16" AR400 floor ILO Std (Mild Steel)	\$ 1,725
1.51	1/4" AR400 floor ILO Std (Mild Steel)	\$ 2,659
1.52	44"-10 gauge sides ILO Std 36" sides (Mild Steel)	\$ 362
1.53	36"-7 gauge sides ILO Std 36" sides (Mild Steel)	\$ 654
1.54	44"-7 gauge sides ILO Std 36" sides (Mild Steel) (7GA TR)	\$ 1,149
1.55	36"-3/16" AR400 sides ILO Std 36" sides (Mild Steel) (7GA TR/RR)	\$ 4,512
1.56	44"-3/16" AR400 sides ILO Std 36" sides (Mild Steel) (7GA TR/RR)	\$ 5,103
1.57	36"-10 gauge sides ILO Std 36" sides (SS201)	\$ 9,602
1.58	44"-10 gauge sides ILO Std 36" sides (SS201)	\$ 10,981
1.59	36"-7 gauge sides ILO Std 36" sides (SS201)	\$ 12,301
1.60	44"-7 gauge sides ILO Std 36" sides (SS201) (7GA TR/RR)	\$ 14,305
1.61	Flush sides and tailgate (No Charge Option)	\$ -
1.62	Double horizontal side brace ILO Std (Mild Steel)	\$ 335
1.63	Double horizontal side brace ILO Std (SS201)	\$ 834
1.64	Triple horizontal side brace ILO Std (Mild Steel) (44" SIDE BODIES ONLY)	\$ 667
1.65	Triple horizontal side brace ILO Std (SS201) (44" SIDE BODIES ONLY)	\$ 1,668
1.68	Walk rail, 2" SURE STEP full length (SS201) Both Sides	\$ 776
1.69	3/4" Round tarp rail both sides (Mild Steel) On side brace	\$ 348
1.70	3/4" Round tarp rail both sides (SS304) On side brace	\$ 583
1.71	8" Channel Boxed Bolt-in Side Boards (Mild Steel)	\$ 1,946
1.72	8" Channel Boxed Bolt-in Side Boards (201 Stainless Steel)	\$ 2,459
1.73	1-1/2" wood side boards	\$ 683
1.74	1-1/2" x 7-1/2" 14' Fiberforce composite side boards	\$ 824

SEE "1.0 Box (Options) Page" for additional accessories & options

	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Mark E, 16' Body
	List Truck Type Box Fits	Tandem Axle with 144" CT
	Box Style	Cross Memberless
	Width & Length of Box	16' long x 96" width
	Side Panel Description	36"-10 gauge high sides, grade 50, 65000 PSI, 1 piece contoured construction with formed horizontal weld on side brace, Flat top dirt shedding top rail and side braces, 2" board pockets
	Front Panel Description	60"-10 gauge, grade 50, 65000 PSI steel
	Floor Description	1- piece 3/16" HSLA grade 50, 65000 PSI steel, Integral 5" floor to side radius
	Corner Post Description	Front contoured 10 gauge, grade 50, 65000 PSI steel Rear 4 3/4" x 12", 7 gauge full depth, tied to 8" steel flush rear apron.
	Under Structure Description	8" structural steel "I" beams (Tele hoist)
	Tailgate Description	44" -10 gauge, grade 50, 65000 PSI steel, with one horizontal brace
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting, package, rubber grommets with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,675
	TOTAL PRICE:	\$ 14,183

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
Box Options		
1.4	Installation Price of Henderson Model Mark E Body	\$ 1,521
1.5	Installation Price of Henderson Model Mark E Body	\$ 10,794
1.6	Deduct front corner post (No Charge)	\$ -
1.7	Mark "E" Asphalt style, slopes rear end and tailgate ILO Std	\$ 294
1.8	Heated Body, (Floor/Rub rail) req 12V regen signal, No UB Hoist (MKE-TA) (Uses 1/4 Mild Steel Formed Longsills ILO Ibeam) (upfitter supplied diverter) (\$ per foot of body length)	\$ 177
1.9	Install heated body portion	\$ 6,223
1.50	3/16" AR400 floor ILO Std (Mild Steel)	\$ 1,836
1.51	1/4" AR400 floor ILO Std (Mild Steel)	\$ 2,833
1.52	44"-10 gauge sides ILO Std 36" sides (Mild Steel)	\$ 416
1.53	36"-7 gauge sides ILO Std 36" sides (Mild Steel)	\$ 674
1.54	44"-7 gauge sides ILO Std 36" sides (Mild Steel) (7GA TR)	\$ 1,191
1.55	36"-3/16" AR400 sides ILO Std 36" sides (Mild Steel) (7GA TR/RR)	\$ 4,718
1.56	44"-3/16" AR400 sides ILO Std 36" sides (Mild Steel) (7GA TR/RR)	\$ 5,369
1.57	36"-10 gauge sides ILO Std 36" sides (SS201)	\$ 9,870
1.58	44"-10 gauge sides ILO Std 36" sides (SS201)	\$ 11,328
1.59	36"-7 gauge sides ILO Std 36" sides (SS201)	\$ 12,674
1.60	44"-7 gauge sides ILO Std 36" sides (SS201) (7GA TR/RR)	\$ 14,804
1.61	Flush sides and tailgate (No Charge Option)	\$ -
1.62	Double horizontal side brace ILO Std (Mild Steel)	\$ 344
1.63	Double horizontal side brace ILO Std (SS201)	\$ 877
1.64	Triple horizontal side brace ILO Std (Mild Steel) (44" SIDE BODIES ONLY)	\$ 692
1.65	Triple horizontal side brace ILO Std (SS201) (44" SIDE BODIES ONLY)	\$ 1,758
1.68	Walk rail, 2" SURE STEP full length (SS201) Both Sides	\$ 830
1.69	3/4" Round tarp rail both sides (Mild Steel) On side brace	\$ 371
1.70	3/4" Round tarp rail both sides (SS304) On side brace	\$ 622
1.71	8" Channel Boxed Bolt-in Side Boards (Mild Steel)	\$ 1,999
1.72	8" Channel Boxed Bolt-in Side Boards (201 Stainless Steel)	\$ 2,536
1.73	1-1/2" wood side boards	\$ 753

SEE "1.0 Box (Options) Page" for additional accessories & options

	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Mark E, 17' Body
	List Truck Type Box Fits	Tandem Axle with 156" CT
	Box Style	Cross Memberless
	Width & Length of Box	17' long x 96" width
	Side Panel Description	36"-10 gauge high sides, grade 50, 65000 PSI, 1 piece contoured construction with formed horizontal weld on side brace, Flat top dirt shedding top rail and side braces, 2" board pockets
	Front Panel Description	60"-10 gauge, grade 50, 65000 PSI steel
	Floor Description	1- piece 3/16" HSLA grade 50, 65000 PSI steel, Integral 5" floor to side radius
	Corner Post Description	Front contoured 10 gauge, grade 50, 65000 PSI steel Rear 4 ¾" x 12", 7 gauge full depth, tied to 8" steel flush rear apron.
	Under Structure Description	8" structural steel "I" beams (Tele hoist)
	Tailgate Description	44" -10 gauge, grade 50, 65000 PSI steel, with one horizontal brace
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting, package, rubber grommets with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,743
TOTAL PRICE:		\$ 14,444

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
Box Options		
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Model Mark E Body	\$ 10,794
1.6	Deduct front corner post (No Charge)	\$ -
1.7	Mark "E" Asphalt style, slopes rear end and tailgate ILO Std	\$ 294
1.8	Heated Body, (Floor/Rub rail) req 12V regen signal, No UB Hoist (MKE-TA) (Uses 1/4 Mild Steel Formed Longsills ILO Ibeam) (upfitter supplied diverter) (\$ per foot of body length)	\$ 177
1.9	Install heated body portion	\$ 6,223
1.50	3/16" AR400 floor ILO Std (Mild Steel)	\$ 1,953
1.51	1/4" AR400 floor ILO Std (Mild Steel)	\$ 3,013
1.52	44"-10 gauge sides ILO Std 36" sides (Mild Steel)	\$ 471
1.53	36"-7 gauge sides ILO Std 36" sides (Mild Steel)	\$ 698
1.54	44"-7 gauge sides ILO Std 36" sides (Mild Steel) (7GA TR)	\$ 1,234
1.55	36"-3/16" AR400 sides ILO Std 36" sides (Mild Steel) (7GA TR/RR)	\$ 4,922
1.56	44"-3/16" AR400 sides ILO Std 36" sides (Mild Steel) (7GA TR/RR)	\$ 5,639
1.57	36"-10 gauge sides ILO Std 36" sides (SS201)	\$ 10,137
1.58	44"-10 gauge sides ILO Std 36" sides (SS201)	\$ 11,676
1.59	36"-7 gauge sides ILO Std 36" sides (SS201)	\$ 13,048
1.60	44"-7 gauge sides ILO Std 36" sides (SS201) (7GA TR/RR)	\$ 15,297
1.61	Flush sides and tailgate (No Charge Option)	\$ -
1.62	Double horizontal side brace ILO Std (Mild Steel)	\$ 357
1.63	Double horizontal side brace ILO Std (SS201)	\$ 927
1.64	Triple horizontal side brace ILO Std (Mild Steel) (44" SIDE BODIES ONLY)	\$ 715
1.65	Triple horizontal side brace ILO Std (SS201) (44" SIDE BODIES ONLY)	\$ 1,853
1.68	Walk rail, 2" SURE STEP full length (SS201) Both Sides	\$ 882
1.69	3/4" Round tarp rail both sides (Mild Steel) On side brace	\$ 393
1.70	3/4" Round tarp rail both sides (SS304) On side brace	\$ 660
1.71	8" Channel Boxed Bolt-in Side Boards (Mild Steel)	\$ 2,056
1.72	8" Channel Boxed Bolt-in Side Boards (201 Stainless Steel)	\$ 2,615
1.73	1-1/2" wood side boards	\$ 777

SEE "1.0 Box (Options) Page" for additional accessories & options

Cost per loaded mile for pickup and or delivery of vehicle (if applicable):		\$ 7
Delivery Starting Point City, State, & Zip:		
Bloomington, MN 55420		
Body Shop Rate	\$	165
Mechanic Shop Rate	\$	165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Mark E, 18' Body
	List Truck Type Box Fits	Tandem Axle with 168" CT
	Box Style	Cross Memberless
	Width & Length of Box	18' long x 96" width
	Side Panel Description	36"-10 gauge high sides, grade 50, 65000 PSI, 1 piece contoured construction with formed horizontal weld on side brace, Flat top dirt shedding top rail and side braces, 2" board pockets
	Front Panel Description	60"-10 gauge, grade 50, 65000 PSI steel
	Floor Description	1- piece 3/16" HSLA grade 50, 65000 PSI steel, Integral 5" floor to side radius
	Corner Post Description	Front contoured 10 gauge, grade 50, 65000 PSI steel Rear 4 3/4" x 12", 7 gauge full depth, tied to 8" steel flush rear apron.
	Under Structure Description	8" structural steel "I" beams (Tele hoist)
	Tailgate Description	44" -10 gauge, grade 50, 65000 PSI steel, with one horizontal brace
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting, package, rubber grommets with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes <input type="checkbox"/> or No <input checked="" type="checkbox"/>
	Is Box Painted?	Yes <input type="checkbox"/> or No <input checked="" type="checkbox"/>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,812
	TOTAL PRICE:	\$ 14,452

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
	Box Options	
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Model Mark E Body	\$ 10,794
1.6	Deduct front corner post (No Charge)	\$ -
1.7	Mark "E" Asphalt style, slopes rear end and tailgate ILO Std	\$ 294
1.8	Heated Body, (Floor/Rub rail) req 12V regen signal, No UB Hoist (MKE-TA) (Uses 1/4 Mild Steel Formed Longsills ILO Ibeam) (upfitter supplied diverter) (\$ per foot of body length)	\$ 177
1.9	Install heated body portion	\$ 6,223
1.50	3/16" AR400 floor ILO Std (Mild Steel)	\$ 2,067
1.51	1/4" AR400 floor ILO Std (Mild Steel)	\$ 3,192
1.52	44"-10 gauge sides ILO Std 36" sides (Mild Steel)	\$ 495
1.53	36"-7 gauge sides ILO Std 36" sides (Mild Steel)	\$ 724
1.54	44"-7 gauge sides ILO Std 36" sides (Mild Steel) (7GA TR)	\$ 1,311
1.55	36"-3/16" AR400 sides ILO Std 36" sides (Mild Steel) (7GA TR/RR)	\$ 5,040
1.56	44"-3/16" AR400 sides ILO Std 36" sides (Mild Steel) (7GA TR/RR)	\$ 5,789
1.57	36"-10 gauge sides ILO Std 36" sides (SS201)	\$ 10,332
1.58	44"-10 gauge sides ILO Std 36" sides (SS201)	\$ 11,915
1.59	36"-7 gauge sides ILO Std 36" sides (SS201)	\$ 13,351
1.60	44"-7 gauge sides ILO Std 36" sides (SS201) (7GA TR/RR)	\$ 15,667
1.61	Flush sides and tailgate (No Charge Option)	\$ -
1.62	Double horizontal side brace ILO Std (Mild Steel)	\$ 368
1.63	Double horizontal side brace ILO Std (SS201)	\$ 973
1.64	Triple horizontal side brace ILO Std (Mild Steel) (44" SIDE BODIES ONLY)	\$ 737
1.65	Triple horizontal side brace ILO Std (SS201) (44" SIDE BODIES ONLY)	\$ 1,945
1.68	Walk rail, 2" SURE STEP full length (SS201) Both Sides	\$ 932
1.69	3/4" Round tarp rail both sides (Mild Steel) On side brace	\$ 416
1.70	3/4" Round tarp rail both sides (SS304) On side brace	\$ 698
1.71	8" Channel Boxed Bolt-in Side Boards (Mild Steel)	\$ 2,110
1.72	8" Channel Boxed Bolt-in Side Boards (201 Stainless Steel)	\$ 2,691
1.73	1-1/2" wood side boards	\$ 777

SEE "1.0 Box (Options) Page" for additional accessories & options

	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson 1096-SA Elliptical Body
	List Truck Type Box Fits	Single Axle with 84" CA
	Box Style	Cross Memberless, Elliptical
	Width & Length of Box	10' long x 96" width
	Side Panel Description	30" high sides, 3/16" AR400, 1 piece 18" radius, 7ga Top Rail corner to floor construction
	Front Panel Description	3/16" AR400
	Floor Description	One piece 3/16" AR400
	Corner Post Description	5 3/4" x 12", 7 gauge full depth, sloped top / tarp friendly, tied to 8" rear apron tailgate latch reinforcements.
	Under Structure Description	5" structural steel "I" beams (tele Hoist)
	Tailgate Description	38" one piece, 3/16" AR400 Tailgate sheet 10 gauge grade 50 65000 PSI, boxed dirt shedding tailgate brace, sloping
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting package rubber grommeted with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 3,933
	TOTAL PRICE:	\$ 14,812

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
Box Options		
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Elliptical Body	\$ 10,706
1.21	¼" AR400 floor ILO Std (Mild Steel)	\$ 538
1.22	7 gauge sides and ends ILO Std (SS201)	\$ 6,540
1.24	4.75" Anti-slip Walkrail (201 Stainless Steel) per side (Removeable)	\$ 1,020
1.25	Flush sides and tailgate (No Charge Option)	\$ -
SEE "1.0 Box (Options) Page" for additional accessories & options		
	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	Aaron Carlson	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson 1196-SA Elliptical Body
	List Truck Type Box Fits	Single Axle with 96" CA
	Box Style	Cross Memberless, Elliptical
	Width & Length of Box	11' long x 96" width
	Side Panel Description	30" high sides, 3/16" AR400, 1 piece 18" radius corner to floor construction
	Front Panel Description	52" high, 3/16" AR400
	Floor Description	One piece 3/16" AR400
	Corner Post Description	5 3/4" x 12", 7 gauge full depth, sloped top / tarp friendly, tied to 8" rear apron with 1/4" plate steel tailgate latch reinforcements.
	Under Structure Description	5" structural steel "I" beams
	Tailgate Description	38" one piece, 3/16" AR400 Tailgate sheet, 10 gauge, grade 50 65000 PSI, boxed dirt shedding tailgate brace, sloping
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting, package, rubber grommets with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,001
	TOTAL PRICE:	\$ 15,517

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Elliptical Body	\$ 10,706
1.21	¼" AR400 floor ILO Std (Mild Steel)	\$ 645
1.22	7 gauge sides and ends ILO Std (SS201)	\$ 5,773
1.24	4.75" Anti-slip Walkrail (201 Stainless Steel) per side (Removeable)	\$ 1,067
1.25	Flush sides and tailgate (No Charge Option)	\$ -

SEE "1.0 Box (Options) Page" for additional accessories & options

	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mqxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson 1296-SA Elliptical Body
	List Truck Type Box Fits	Single Axle with 108" CA
	Box Style	Cross Memberless, Elliptical
	Width & Length of Box	12' long x 96" width
	Side Panel Description	30" high sides, 3/16" AR400, 1 piece 18" radius, 7ga Top Rail corner to floor construction
	Front Panel Description	3/16" AR400
	Floor Description	One piece 3/16" AR400
	Corner Post Description	4-3/4" x 12", 7 gauge full depth, sloped top / tarp friendly, tied to 8" rear apron tailgate latch reinforcements.
	Under Structure Description	5" structural steel "I" beams (tele Hoist)
	Tailgate Description	38" one piece 3/16" AR400 Tailgate sheet, 10 gauge grade 50 65000 PSI, boxed dirt shedding tailgate brace, sloping
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting, package, rubber grommets with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,069
	TOTAL PRICE:	\$ 16,727

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
Box Options		
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Elliptical Body	\$ 10,706
1.21	¼" AR400 floor ILO Std (Mild Steel)	\$ 707
1.22	7 gauge sides and ends ILO Std (SS201)	\$ 5,987
1.24	4.75" Anti-slip Walkrail (201 Stainless Steel) per side (Removeable)	\$ 1,113
1.25	Flush sides and tailgate (No Charge Option)	\$ -
SEE "1.0 Box (Options) Page" for additional accessories & options		
	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson 1396-TA Elliptical Body
	List Truck Type Box Fits	Tandem Axle with 108" CT
	Box Style	Cross Memberless, Elliptical
	Width & Length of Box	13' long x 96" width
	Side Panel Description	44" high sides, 3/16" AR400, 1 piece 18" radius, 7ga Top Rail corner to floor construction
	Front Panel Description	60" high, 3/16" AR400
	Floor Description	One piece 3/16" AR400
	Corner Post Description	4-3/4" x 12", 7 gauge full depth, sloped top / tarp friendly, tied to 8" rear apron tailgate latch reinforcements.
	Under Structure Description	8" structural steel "I" beams
	Tailgate Description	52" one piece, 3/16" AR400 Tailgate sheet, 10 gauge grade 50
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting package, rubber grommeted with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes or No <u>X</u>
	Is Box Painted?	Yes or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,139
	TOTAL PRICE:	\$ 18,752

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Elliptical Body	\$ 10,706
1.20	¼" AR400 floor ILO Std (Mild Steel)	\$ 814
1.21	7 gauge sides and ends ILO Std (SS201)	\$ 6,797
1.23	4.75" Anti-slip Walkrail (201 Stainless Steel) per side (Removeable)	\$ 1,289
1.24	Flush sides and tailgate (No Charge Option)	\$ -
SEE "1.0 Box (Options) Page" for additional accessories & options		
	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mqxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson 1496-TA Elliptical Body
	List Truck Type Box Fits	Tandem Axle with 120" CT
	Box Style	Cross Memberless, Elliptical
	Width & Length of Box	14' long x 96" width
	Side Panel Description	44" high sides, 3/16" AR400, 1 piece 18" radius, 7ga Top Rail corner to floor construction
	Front Panel Description	60" high, 3/16" AR400
	Floor Description	One piece 3/16" AR400
	Corner Post Description	5 3/4" x 12", 7 gauge full depth, sloped top / tarp friendly, tied to 8" rear apron tailgate latch reinforcements.
	Under Structure Description	8" structural steel "I" beams
	Tailgate Description	52" one piece, 3/16" AR400 Tailgate sheet, 10 gauge grade 50
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting, package, rubber grommeted with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,537
	TOTAL PRICE:	\$ 19,214

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Elliptical Body	\$ 10,706
1.20	¼" AR400 floor ILO Std (Mild Steel)	\$ 878
1.21	7 gauge sides and ends ILO Std (SS201)	\$ 7,007
1.23	4.75" Anti-slip Walkrail (201 Stainless Steel) per side (Removeable)	\$ 1,335
1.24	Flush sides and tailgate (No Charge Option)	\$ -

SEE "1.0 Box (Options) Page" for additional accessories & options

	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson 1596-TA Elliptical Body
	List Truck Type Box Fits	Tandem Axle with 132" CT
	Box Style	Cross Memberless, Elliptical
	Width & Length of Box	15' long x 96" width
	Side Panel Description	44" high sides, 3/16" AR400, 1 piece 18" radius, 7ga Top Rail corner to floor construction
	Front Panel Description	60" high, 3/16" AR400
	Floor Description	One piece 3/16" AR400
	Corner Post Description	5 3/4" x 12", 7 gauge full depth, sloped top / tarp friendly, tied to 8" rear apron tailgate latch reinforcements.
	Under Structure Description	8" structural steel "I" beams
	Tailgate Description	52" one piece, 3/16" AR400 Tailgate sheet, 10gauge grade 50
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting, package, rubber grommets with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,605
TOTAL PRICE:		\$ 19,760

Spec #	Description	Answer
Box Options		
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Elliptical Body	\$ 10,706
1.20	¼" AR400 floor ILO Std (Mild Steel)	\$ 937
1.21	7 gauge sides and ends ILO Std (SS201)	\$ 7,216
1.23	4.75" Anti-slip Walkrail (201 Stainless Steel) per side (Removeable)	\$ 1,381
1.24	Flush sides and tailgate (No Charge Option)	\$ -

SEE "1.0 Box (Options) Page" for additional accessories & options

	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson 1696-TA Elliptical Body
	List Truck Type Box Fits	Tandem Axle with 144" CT
	Box Style	Cross Memberless, Elliptical
	Width & Length of Box	16' long x 96" width
	Side Panel Description	44" high sides, 3/16" AR400, 1 piece 18" radius, 7ga Top Rail corner to floor construction
	Front Panel Description	60" high, 3/16" AR400
	Floor Description	One piece 3/16" AR400
	Corner Post Description	4-3/4" x 12", 7 gauge full depth, sloped top / tarp friendly, tied to 8" rear apron tailgate latch reinforcements.
	Under Structure Description	8" structural steel "I" beams
	Tailgate Description	52" one piece, 3/16" AR400 Tailgate sheet, 10 gauge grade 50
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting package rubber grommited with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No X ___
	Is Box Painted?	Yes ___ or No X ___
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,675
	TOTAL PRICE:	\$ 20,295

Spec #	Description	Answer
	Box Options	
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Elliptical Body	\$ 10,706
1.20	1/4" AR400 floor ILO Std (Mild Steel)	\$ 937
1.21	7 gauge sides and ends ILO Std (SS201)	\$ 7,216
1.23	4.75" Anti-slip Walkrail (201 Stainless Steel) per side (Removeable)	\$ 1,381
1.24	Flush sides and tailgate (No Charge Option)	\$ -
	SEE "1.0 Box (Options) Page" for additional accessories & options	
	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson 1796-TA Elliptical Body
	List Truck Type Box Fits	Tandem Axle with 156" CT
	Box Style	Cross Memberless, Elliptical
	Width & Length of Box	17' long x 96" width
	Side Panel Description	44" high sides, 3/16" AR400, 1 piece 18" radius, 7ga Top Rail corner to floor construction
	Front Panel Description	60" high, 3/16" AR400
	Floor Description	One piece 3/16" AR400
	Corner Post Description	4-3/4" x 12", 7 gauge full depth, sloped top / tarp friendly, tied to 8" rear apron tailgate latch reinforcements.
	Under Structure Description	8" structural steel "I" beams
	Tailgate Description	52" one piece, 3/16" AR400 Tailgate sheet, 10gauge grade 50
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting, package, rubber grommets with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,743
	TOTAL PRICE:	\$ 21,017

Spec #	Description	Answer
	Box Options	
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Elliptical Body	\$ 10,706
1.20	¼" AR400 floor ILO Std (Mild Steel)	\$ 1,063
1.21	7 gauge sides and ends ILO Std (SS201)	\$ 7,410
1.23	4.75" Anti-slip Walkrail (201 Stainless Steel) per side (Removeable)	\$ 1,472
1.24	Flush sides and tailgate (No Charge Option)	\$ -

SEE "1.0 Box (Options) Page" for additional accessories & options

	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Muni 2 10 Body
	List Truck Type Box Fits	Single Axle with 84" CA
	Box Style	Crossmemberless design with 22 degree sloping sides and live (conveyor) floor
	Width & Length of Box	10' long x 96" width
	Side Panel Description	36" high sides, grade 50, 65000 PSI, 1 piece sloping construction, 6" radius corners, dirt shedding boxed top rail and 4" board pockets
	Front Panel Description	10 gauge, grade 50, 65000 PSI steel
	Floor Description	28" main conveyor chain. 15" spreader apron, 1/4" AR400 conveyor floor. 8 tooth, 2" ID diameter sprockets driven by 25:1 planetary gear case driven by piston type drive motor. Stainless steel inner / outer longills. Rear discharge with spinner assembly.
	Corner Post Description	5" x 12 3/4", 7 gauge full depth, tied to 12" steel rear apron with 1/4" plate steel tailgate latch reinforcements
	Under Structure Description	Stainless steel formed long sills with telescopic hoist
	Tailgate Description	7-gauge steel, grade 50 65000 PSI, boxed tailgate brace, sloping braces. 1 1/4" upper / lower pins
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting package rubber grommited with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 3,933
	TOTAL PRICE:	\$ 26,125

Spec #	Description	Answer
	Box Options	
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson MuniBody	\$ 9,937
1.63	22 degree sloped option (No Charge)	\$ -
1.64	35 degree sloped option (No Charge)	\$ -
1.65	Munibody Flat Floor Upgrade, inc single side brace, AR floor (Mild Bodies) (No auger)	\$ 4,050
1.66	Munibody Flat Floor Upgrade, inc single side brace, AR floor (SS Bodies) (No Auger)	\$ 4,050
1.6	External Dog House option	\$ 2,343
1.7	Front cross conveyor and rear discharge (9-12) (SA pin to pin cylinder)	\$ 2,656
1.8	Front cross conveyor and rear discharge (13-16) (SA pin to pin cylinder)	\$ 2,656
1.9	Front "Center" and rear discharge 9'-12' bodies	\$ 412
1.10	Front "Center" and rear discharge 13'-17' bodies	\$ 3,836
1.11	Conveyor chain oiling system, installed	\$ 323
1.12	Fold up side ladder	\$ 843
1.13	Fold up side ladder, stainless steel	\$ 1,377
1.14	Polyurethane spinner disc in lieu of steel	\$ 233
1.15	Rear asphalt patching pan, with chute and mount (front/rear discharge)	\$ 850
1.16	Rear asphalt patching pan, mild steel (rear discharge only)	\$ 290
1.17	Rear spinner assembly with chute and mount	\$ 2,539
1.18	Front berm chute for right hand discharge, mild steel	\$ 235
1.19	Rear berm chute, mild steel	\$ 886
1.20	Fender mounted tool boxes on both sides – Mild Steel 13' and longer	\$ 3,073
1.21	Fender mounted tool boxes on both sides – Mild Steel 12' and shorter	\$ 2,789
1.22	Fender mounted tool box on CS or SS – Mild steel 13' and longer	\$ 1,702
1.23	Fender mounted tool box on CS or SS – Mild steel 12' and shorter	\$ 1,560
1.24	Fender mounted tool boxes on both sides – 13' and longer SS	\$ 4,983
1.25	Fender mounted tool boxes on both sides – 12' and shorter SS	\$ 4,035
1.26	Fender mounted tool box on CS or SS – 13' and longer SS	\$ 2,657
1.27	Fender mounted tool box on CS or SS – 12' and shorter SS	\$ 2,183
1.28	75 gallon poly prewet tank on both sides (22deg or 35deg muni)	\$ 2,438
1.29	75 gallon poly prewet tank on drivers side or passenger side (22deg or 35deg muni)	\$ 1,384
1.30	105 gallon poly prewet tank on both sides (22deg muni)	\$ 4,041
1.31	105 gallon poly prewet tank on drivers side or passenger side (22deg muni)	\$ 2,185
1.32	150 gallon poly prewet tank on both sides (22deg muni)	\$ 5,927
1.33	150 gallon poly prewet tank on drivers side or passenge side (22deg muni)	\$ 3,129
1.34	115 gallon poly prewet tank on both sides (35deg muni)	\$ 4,309
1.35	115 gallon poly prewet tank on drivers side or passenger side (35deg muni)	\$ 2,320
1.36	165 gallon poly prewet tank on both sides (35deg muni)	\$ 4,236
1.37	165 gallon poly prewet tank on drivers side or passenger side (35deg muni)	\$ 2,283
1.38	230 gallon poly prewet tank on both sides (35deg muni)	\$ 6,229
1.39	230 gallon poly prewet tank on drivers side or passenge side (35deg muni)	\$ 3,279
1.40	Cradle mount hydraulic reservoir (external dog house only)	\$ 709
1.41	Side mount oil reservoir (internal doghouse)	\$ 327
1.50	42" Steel Sides & Ends / 7 ga grade 50	\$ 393
1.51	48" Steel Sides & Ends / 7 ga grade 50	\$ 818
1.52	3/16" AR400 Sides/Ends/Tail gate in lieu of standard 7 ga grade 50	\$ 4,174
1.54	36" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 14,768
1.55	42" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 15,658
1.56	48" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 16,408
1.57	Top grate screens – Standard 3/8" rod x 3/8" rod	\$ 2,659
1.58	Top grate screens – Heavy Duty 3/8" rod thru 2" flat	\$ 3,503
1.59	Sloped Mild Steel side boards	\$ 1,877
1.60	Sloped 201SS Steel side boards	\$ 3,310
1.61	Underbody Pan – stainless steel	\$ 811
1.62	Rubber belt over chain conveyor	\$ 2,502
1.63	Double conveyor cross bars	\$ 1,027
1.64	Steel conveyor cover	\$ 1,639
1.65	Dual auger option (INCLUDES STANDARD TOP SCREENS ABOVE)	\$ 8,017

SEE "1.0 Box (Options) Page" for additional accessories & options

	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$	7
	Delivery Starting Point City, State, & Zip:		
	Bloomington, MN 55420		
	Body Shop Rate	\$	165
	Mechanic Shop Rate	\$	165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Muni 2 11' Body
	List Truck Type Box Fits	Single Axle with 96" CA
	Box Style	Crossmemberless design with 22 degree sloping sides and live (conveyor) floor
	Width & Length of Box	11' long x 96" width
	Side Panel Description	36" high sides, grade 50, 65000 PSI, 1 piece sloping construction, 6" radius corners, dirt shedding boxed top rail and 4" board pockets
	Front Panel Description	10 gauge, grade 50, 65000 PSI steel
	Floor Description	28" main conveyor chain. 15" spreader apron, 1/4" AR400 conveyor floor. 8 tooth, 2" ID diameter sprockets driven by 25:1 planetary gear case driven by piston type drive motor. Stainless steel inner / outer longills. Rear discharge with spinner assembly.
	Corner Post Description	5" x 12 3/4", 7 gauge full depth, tied to 12" steel rear apron with 1/4" plate steel tailgate latch reinforcements
	Under Structure Description	Stainless steel formed long sills with telescopic hoist
	Tailgate Description	7-gauge steel, grade 50 65000 PSI, boxed tailgate brace, sloping braces. 1 1/4" upper / lower pins
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting package rubber grommited with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,001
	TOTAL PRICE:	\$ 27,434

Spec #	Description	Answer
	Box Options	
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson MuniBody	\$ 9,937
1.63	22 degree sloped option (No Charge)	\$ -
1.64	35 degree sloped option (No Charge)	\$ -
1.65	Munibody Flat Floor Upgrade, inc single side brace, AR floor (Mild Bodies) (No auger)	\$ 4,050
1.66	Munibody Flat Floor Upgrade, inc single side brace, AR floor (SS Bodies) (No Auger)	\$ 4,050
1.6	External Dog House option	\$ 2,343
1.7	Front cross conveyor and rear discharge (9-12) (SA pin to pin cylinder)	\$ 2,656
1.8	Front cross conveyor and rear discharge (13-16) (SA pin to pin cylinder)	\$ 2,656
1.9	Front "Center" and rear discharge 9'-12' bodies	\$ 412
1.10	Front "Center" and rear discharge 13'-17' bodies	\$ 3,836
1.11	Conveyor chain oiling system, installed	\$ 323
1.12	Fold up side ladder	\$ 843
1.13	Fold up side ladder, stainless steel	\$ 1,377
1.14	Polyurethane spinner disc in lieu of steel	\$ 233
1.15	Rear asphalt patching pan, with chute and mount (front/rear discharge)	\$ 850
1.16	Rear asphalt patching pan, mild steel (rear discharge only)	\$ 290
1.17	Rear spinner assembly with chute and mount	\$ 2,539
1.18	Front berm chute for right hand discharge, mild steel	\$ 235
1.19	Rear berm chute, mild steel	\$ 886
1.20	Fender mounted tool boxes on both sides – Mild Steel 13' and longer	\$ 3,073
1.21	Fender mounted tool boxes on both sides – Mild Steel 12' and shorter	\$ 2,789
1.22	Fender mounted tool box on CS or SS – Mild steel 13' and longer	\$ 1,702
1.23	Fender mounted tool box on CS or SS – Mild steel 12' and shorter	\$ 1,560
1.24	Fender mounted tool boxes on both sides – 13' and longer SS	\$ 4,983
1.25	Fender mounted tool boxes on both sides – 12' and shorter SS	\$ 4,035
1.26	Fender mounted tool box on CS or SS – 13' and longer SS	\$ 2,657
1.27	Fender mounted tool box on CS or SS – 12' and shorter SS	\$ 2,183
1.28	75 gallon poly prewet tank on both sides (22deg or 35deg muni)	\$ 2,438
1.29	75 gallon poly prewet tank on drivers side or passenger side (22deg or 35deg muni)	\$ 1,384
1.30	105 gallon poly prewet tank on both sides (22deg muni)	\$ 4,041
1.31	105 gallon poly prewet tank on drivers side or passenger side (22deg muni)	\$ 2,185
1.32	150 gallon poly prewet tank on both sides (22deg muni)	\$ 5,927
1.33	150 gallon poly prewet tank on drivers side or passenge side (22deg muni)	\$ 3,129
1.34	115 gallon poly prewet tank on both sides (35deg muni)	\$ 4,309
1.35	115 gallon poly prewet tank on drivers side or passenger side (35deg muni)	\$ 2,320
1.36	165 gallon poly prewet tank on both sides (35deg muni)	\$ 4,236
1.37	165 gallon poly prewet tank on drivers side or passenger side (35deg muni)	\$ 2,283
1.38	230 gallon poly prewet tank on both sides (35deg muni)	\$ 6,229
1.39	230 gallon poly prewet tank on drivers side or passenge side (35deg muni)	\$ 3,279
1.40	Cradle mount hydraulic reservoir (external dog house only)	\$ 709
1.41	Side mount oil reservoir (internal doghouse)	\$ 327
1.50	42" Steel Sides & Ends / 7 ga grade 50	\$ 406
1.51	48" Steel Sides & Ends / 7 ga grade 50	\$ 841
1.52	3/16" AR400 Sides/Ends/Tail gate in lieu of standard 7 ga grade 50	\$ 4,329
1.53	36" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 15,415
1.54	42" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 16,346
1.55	48" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 17,055
1.56	Top grate screens – Standard 3/8" rod x 3/8" rod	\$ 2,880
1.57	Top grate screens – Heavy Duty 3/8" rod thru 2" flat	\$ 3,836
1.58	Sloped Mild Steel side boards	\$ 1,420
1.59	Sloped 201SS Steel side boards	\$ 2,937
1.60	Underbody Pan – stainless steel	\$ 869
1.61	Rubber belt over chain conveyor	\$ 2,743
1.62	Double conveyor cross bars	\$ 1,168
1.63	Steel conveyor cover	\$ 1,808
1.64	Dual auger option (INCLUDES STANDARD TOP SCREENS ABOVE)	\$ 8,459

SEE "1.0 Box (Options) Page" for additional accessories & options

--	--	--

Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$	7
Delivery Starting Point City, State, & Zip:		
	Bloomington, MN 55420	
Body Shop Rate	\$	165
Mechanic Shop Rate	\$	165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Muni 2 12' Body
	List Truck Type Box Fits	Single Axle with 96" CA
	Box Style	Crossmemberless design with 22 degree sloping sides and live (conveyor) floor
	Width & Length of Box	12' long x 96" width
	Side Panel Description	36" high sides, grade 50, 65000 PSI, 1 piece sloping construction, 6" radius corners, dirt shedding boxed top rail and 4" board pockets
	Front Panel Description	10 gauge, grade 50, 65000 PSI steel
	Floor Description	28" main conveyor chain. 15" spreader apron, 3/16" AR400 conveyor floor. 8 tooth, 2" ID diameter sprockets driven by 25:1 planetary gear case driven by piston type drive motor. Stainless steel inner / outer longills. Rear discharge with spinner assembly.
	Corner Post Description	5" x 12 3/4", 7 gauge full depth, tied to 12" steel rear apron with 1/4" plate steel tailgate latch reinforcements
	Under Structure Description	Stainless steel formed long sills with telescopic hoist
	Tailgate Description	7-gauge steel, grade 50 65000 PSI, boxed tailgate brace, sloping braces. 1 1/4" upper / lower pins
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard lighting, package, rubber grommeted with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes or No X
	Is Box Painted?	Yes or No X
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,069
	TOTAL PRICE:	\$ 28,479

Spec #	Description	Answer
	Box Options	
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson MuniBody	\$ 9,937
1.63	22 degree sloped option (No Charge)	\$ -
1.64	35 degree sloped option (No Charge)	\$ -
1.65	Munibody Flat Floor Upgrade, inc single side brace, AR floor (Mild Bodies) (No auger)	\$ 4,050
1.66	Munibody Flat Floor Upgrade, inc single side brace, AR floor (SS Bodies) (No Auger)	\$ 4,050
1.6	External Dog House option	\$ 2,343
1.7	Front cross conveyor and rear discharge (9-12) (SA pin to pin cylinder)	\$ 2,656
1.8	Front cross conveyor and rear discharge (13-16) (SA pin to pin cylinder)	\$ 2,656
1.9	Front "Center" and rear discharge 9'-12' bodies	\$ 412
1.10	Front "Center" and rear discharge 13'-17' bodies	\$ 3,836
1.11	Conveyor chain oiling system, installed	\$ 323
1.12	Fold up side ladder	\$ 843
1.13	Fold up side ladder, stainless steel	\$ 1,377
1.14	Polyurethane spinner disc in lieu of steel	\$ 233
1.15	Rear asphalt patching pan, with chute and mount (front/rear discharge)	\$ 850
1.16	Rear asphalt patching pan, mild steel (rear discharge only)	\$ 290
1.17	Rear spinner assembly with chute and mount	\$ 2,539
1.18	Front berm chute for right hand discharge, mild steel	\$ 235
1.19	Rear berm chute, mild steel	\$ 886
1.20	Fender mounted tool boxes on both sides – Mild Steel 13' and longer	\$ 3,073
1.21	Fender mounted tool boxes on both sides – Mild Steel 12' and shorter	\$ 2,789
1.22	Fender mounted tool box on CS or SS – Mild steel 13' and longer	\$ 1,702
1.23	Fender mounted tool box on CS or SS – Mild steel 12' and shorter	\$ 1,560
1.24	Fender mounted tool boxes on both sides – 13' and longer SS	\$ 4,983
1.25	Fender mounted tool boxes on both sides – 12' and shorter SS	\$ 4,035
1.26	Fender mounted tool box on CS or SS – 13' and longer SS	\$ 2,657
1.27	Fender mounted tool box on CS or SS – 12' and shorter SS	\$ 2,183
1.28	75 gallon poly prewet tank on both sides (22deg or 35deg muni)	\$ 2,438
1.29	75 gallon poly prewet tank on drivers side or passenger side (22deg or 35deg muni)	\$ 1,384
1.30	105 gallon poly prewet tank on both sides (22deg muni)	\$ 4,041
1.31	105 gallon poly prewet tank on drivers side or passenger side (22deg muni)	\$ 2,185
1.32	150 gallon poly prewet tank on both sides (22deg muni)	\$ 5,927
1.33	150 gallon poly prewet tank on drivers side or passenge side (22deg muni)	\$ 3,129
1.34	115 gallon poly prewet tank on both sides (35deg muni)	\$ 4,309
1.35	115 gallon poly prewet tank on drivers side or passenger side (35deg muni)	\$ 2,320
1.36	165 gallon poly prewet tank on both sides (35deg muni)	\$ 4,236
1.37	165 gallon poly prewet tank on drivers side or passenger side (35deg muni)	\$ 2,283
1.38	230 gallon poly prewet tank on both sides (35deg muni)	\$ 6,229
1.39	230 gallon poly prewet tank on drivers side or passenge side (35deg muni)	\$ 3,279
1.40	Cradle mount hydraulic reservoir (external dog house only)	\$ 709
1.41	Side mount oil reservoir (internal doghouse)	\$ 327
1.50	42" Steel Sides & Ends / 7 ga grade 50	\$ 418
1.51	48" Steel Sides & Ends / 7 ga grade 50	\$ 864
1.52	3/16" AR400 Sides/Ends/Tail gate in lieu of standard 7 ga grade 50	\$ 4,490
1.53	36" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 16,604
1.54	42" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 17,577
1.55	48" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 18,411
1.56	Top grate screens – Standard 3/8" rod x 3/8" rod	\$ 3,100
1.57	Top grate screens – Heavy Duty 3/8" rod thru 2" flat	\$ 4,108
1.58	Sloped Mild Steel side boards	\$ 1,531
1.59	Sloped 201SS Steel side boards	\$ 3,068
1.60	Underbody Pan – stainless steel	\$ 1,092
1.61	Rubber belt over chain conveyor	\$ 3,010
1.62	Double conveyor cross bars	\$ 1,288
1.63	Steel conveyor cover	\$ 1,847
1.64	Dual auger option (INCLUDES STANDARD TOP SCREENS ABOVE)	\$ 8,889

SEE "1.0 Box (Options) Page" for additional accessories & options

Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$	7
Delivery Starting Point City, State, & Zip:		
	Bloomington, MN 55420	
Body Shop Rate	\$	165
Mechanic Shop Rate	\$	165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Muni 2 13' Body
	List Truck Type Box Fits	Tandem Axle with 108" CT
	Box Style	Crossmemberless design with 22 degree sloping sides and live (conveyor) floor
	Width & Length of Box	13' long x 96" width
	Side Panel Description	36" high sides, grade 50, 65000 PSI, 1 piece sloping construction, 6" radius corners, dirt shedding boxed top rail and 4" board pockets
	Front Panel Description	10 gauge, grade 50, 65000 PSI steel
	Floor Description	28" main conveyor chain. 15" spreader apron, 1/4" AR400 conveyor floor. 8 tooth, 2" ID diameter sprockets driven by 25:1 planetary gear case driven by piston type drive motor. Stainless steel inner / outer longsills. Rear discharge with spinner assembly.
	Corner Post Description	5" x 12 3/4", 7 gauge full depth, tied to 12" steel rear apron with 1/4" plate steel tailgate latch reinforcements
	Under Structure Description	Stainless steel formed long sills with telescopic hoist
	Tailgate Description	7-gauge steel, grade 50 65000 PSI, boxed tailgate brace, sloping braces. 1 1/4" upper / lower pins
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting package rubber grommeted with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,139
	TOTAL PRICE:	\$ 30,322

Spec #	Description	Answer
	Box Options	
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson MuniBody	\$ 9,937
1.63	22 degree sloped option (No Charge)	\$ -
1.64	35 degree sloped option (No Charge)	\$ -
1.65	Munibody Flat Floor Upgrade, inc single side brace, AR floor (Mild Bodies) (No auger)	\$ 4,050
1.66	Munibody Flat Floor Upgrade, inc single side brace, AR floor (SS Bodies) (No Auger)	\$ 4,050
1.6	External Dog House option	\$ 2,343
1.7	Front cross conveyor and rear discharge (9-12) (SA pin to pin cylinder)	\$ 2,656
1.8	Front cross conveyor and rear discharge (13-16) (SA pin to pin cylinder)	\$ 2,656
1.9	Front "Center" and rear discharge 9'-12' bodies	\$ 412
1.10	Front "Center" and rear discharge 13'-17' bodies	\$ 3,836
1.11	Conveyor chain oiling system, installed	\$ 323
1.12	Fold up side ladder	\$ 843
1.13	Fold up side ladder, stainless steel	\$ 1,377
1.14	Polyurethane spinner disc in lieu of steel	\$ 233
1.15	Rear asphalt patching pan, with chute and mount (front/rear discharge)	\$ 850
1.16	Rear asphalt patching pan, mild steel (rear discharge only)	\$ 290
1.17	Rear spinner assembly with chute and mount	\$ 2,539
1.18	Front berm chute for right hand discharge, mild steel	\$ 235
1.19	Rear berm chute, mild steel	\$ 886
1.20	Fender mounted tool boxes on both sides – Mild Steel 13' and longer	\$ 3,073
1.21	Fender mounted tool boxes on both sides – Mild Steel 12' and shorter	\$ 2,789
1.22	Fender mounted tool box on CS or SS – Mild steel 13' and longer	\$ 1,702
1.23	Fender mounted tool box on CS or SS – Mild steel 12' and shorter	\$ 1,560
1.24	Fender mounted tool boxes on both sides – 13' and longer SS	\$ 4,983
1.25	Fender mounted tool boxes on both sides – 12' and shorter SS	\$ 4,035
1.26	Fender mounted tool box on CS or SS – 13' and longer SS	\$ 2,657
1.27	Fender mounted tool box on CS or SS – 12' and shorter SS	\$ 2,183
1.28	75 gallon poly prewet tank on both sides (22deg or 35deg muni)	\$ 2,438
1.29	75 gallon poly prewet tank on drivers side or passenger side (22deg or 35deg muni)	\$ 1,384
1.30	105 gallon poly prewet tank on both sides (22deg muni)	\$ 4,041
1.31	105 gallon poly prewet tank on drivers side or passenger side (22deg muni)	\$ 2,185
1.32	150 gallon poly prewet tank on both sides (22deg muni)	\$ 5,927
1.33	150 gallon poly prewet tank on drivers side or passenge side (22deg muni)	\$ 3,129
1.34	115 gallon poly prewet tank on both sides (35deg muni)	\$ 4,309
1.35	115 gallon poly prewet tank on drivers side or passenger side (35deg muni)	\$ 2,320
1.36	165 gallon poly prewet tank on both sides (35deg muni)	\$ 4,236
1.37	165 gallon poly prewet tank on drivers side or passenger side (35deg muni)	\$ 2,283
1.38	230 gallon poly prewet tank on both sides (35deg muni)	\$ 6,229
1.39	230 gallon poly prewet tank on drivers side or passenge side (35deg muni)	\$ 3,279
1.40	Cradle mount hydraulic reservoir (external dog house only)	\$ 709
1.41	Side mount oil reservoir (internal doghouse)	\$ 327
1.50	42" Steel Sides & Ends / 7 ga grade 50	\$ 429
1.51	48" Steel Sides & Ends / 7 ga grade 50	\$ 889
1.52	3/16" AR400 Sides/Ends/Tail gate in lieu of standard 7 ga grade 50	\$ 4,649
1.53	36" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 17,759
1.54	42" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 18,774
1.55	48" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 19,649
1.56	Top grate screens – Standard 3/8" rod x 3/8" rod	\$ 3,332
1.57	Top grate screens – Heavy Duty 3/8" rod thru 2" flat	\$ 4,552
1.58	Sloped Mild Steel side boards	\$ 1,619
1.59	Sloped 201SS Steel side boards	\$ 3,297
1.60	Underbody Pan – stainless steel	\$ 1,178
1.61	Rubber belt over chain conveyor	\$ 3,244
1.62	Double conveyor cross bars	\$ 1,410
1.63	Steel conveyor cover	\$ 1,388
1.64	Dual auger option (INCLUDES STANDARD TOP SCREENS ABOVE)	\$ 9,324

SEE "1.0 Box (Options) Page" for additional accessories & options

	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Muni 2 14' Body
	List Truck Type Box Fits	Tandem Axle with 120" CT
	Box Style	Crossmemberless design with 22 degree sloping sides and live (conveyor) floor
	Width & Length of Box	14' long x 96" width
	Side Panel Description	36" high sides, grade 50, 65000 PSI, 1 piece sloping construction, 6" radius corners, dirt shedding boxed top rail and 4" board pockets
	Front Panel Description	10 gauge, grade 50, 65000 PSI steel
	Floor Description	28" main conveyor chain. 15" spreader apron, 1/4" AR400 conveyor floor. 8 tooth, 2" ID diameter sprockets driven by 25:1 planetary gear case driven by piston type drive motor. Stainless steel inner / outer longills. Rear discharge with spinner assembly.
	Corner Post Description	5" x 12 3/4", 7 gauge full depth, tied to 12" steel rear apron with 1/4" plate steel tailgate latch reinforcements
	Under Structure Description	Stainless steel formed long sills with telescopic hoist
	Tailgate Description	7-gauge steel, grade 50 65000 PSI, boxed tailgate brace, sloping braces. 1 1/4" upper / lower pins
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting package rubber grommited with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes ___ or No <u>X</u>
	Is Box Painted?	Yes ___ or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,537
	TOTAL PRICE:	\$ 31,755

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson MuniBody	\$ 9,937
1.63	22 degree sloped option (No Charge)	\$ -
1.64	35 degree sloped option (No Charge)	\$ -
1.65	Munibody Flat Floor Upgrade, inc single side brace, AR floor (Mild Bodies) (No auger)	\$ 4,050
1.66	Munibody Flat Floor Upgrade, inc single side brace, AR floor (SS Bodies) (No Auger)	\$ 4,050
1.6	External Dog House option	\$ 2,343
1.7	Front cross conveyor and rear discharge (9-12) (SA pin to pin cylinder)	\$ 2,656
1.8	Front cross conveyor and rear discharge (13-16) (SA pin to pin cylinder)	\$ 2,656
1.9	Front "Center" and rear discharge 9'-12' bodies	\$ 412
1.10	Front "Center" and rear discharge 13'-17' bodies	\$ 3,836
1.11	Conveyor chain oiling system, installed	\$ 323
1.12	Fold up side ladder	\$ 843
1.13	Fold up side ladder, stainless steel	\$ 1,377
1.14	Polyurethane spinner disc in lieu of steel	\$ 233
1.15	Rear asphalt patching pan, with chute and mount (front/rear discharge)	\$ 850
1.16	Rear asphalt patching pan, mild steel (rear discharge only)	\$ 290
1.17	Rear spinner assembly with chute and mount	\$ 2,539
1.18	Front berm chute for right hand discharge, mild steel	\$ 235
1.19	Rear berm chute, mild steel	\$ 886
1.20	Fender mounted tool boxes on both sides – Mild Steel 13' and longer	\$ 3,073
1.21	Fender mounted tool boxes on both sides – Mild Steel 12' and shorter	\$ 2,789
1.22	Fender mounted tool box on CS or SS – Mild steel 13' and longer	\$ 1,702
1.23	Fender mounted tool box on CS or SS – Mild steel 12' and shorter	\$ 1,560
1.24	Fender mounted tool boxes on both sides – 13' and longer SS	\$ 4,983
1.25	Fender mounted tool boxes on both sides – 12' and shorter SS	\$ 4,035
1.26	Fender mounted tool box on CS or SS – 13' and longer SS	\$ 2,657
1.27	Fender mounted tool box on CS or SS – 12' and shorter SS	\$ 2,183
1.28	75 gallon poly prewet tank on both sides (22deg or 35deg muni)	\$ 2,438
1.29	75 gallon poly prewet tank on drivers side or passenger side (22deg or 35deg muni)	\$ 1,384
1.30	105 gallon poly prewet tank on both sides (22deg muni)	\$ 4,041
1.31	105 gallon poly prewet tank on drivers side or passenger side (22deg muni)	\$ 2,185
1.32	150 gallon poly prewet tank on both sides (22deg muni)	\$ 5,927
1.33	150 gallon poly prewet tank on drivers side or passenge side (22deg muni)	\$ 3,129
1.34	115 gallon poly prewet tank on both sides (35deg muni)	\$ 4,309
1.35	115 gallon poly prewet tank on drivers side or passenger side (35deg muni)	\$ 2,320
1.36	165 gallon poly prewet tank on both sides (35deg muni)	\$ 4,236
1.37	165 gallon poly prewet tank on drivers side or passenger side (35deg muni)	\$ 2,283
1.38	230 gallon poly prewet tank on both sides (35deg muni)	\$ 6,229
1.39	230 gallon poly prewet tank on drivers side or passenge side (35deg muni)	\$ 3,279
1.40	Cradle mount hydraulic reservoir (external dog house only)	\$ 709
1.41	Side mount oil reservoir (internal doghouse)	\$ 327
1.50	42" Steel Sides & Ends / 7 ga grade 50	\$ 441
1.51	48" Steel Sides & Ends / 7 ga grade 50	\$ 869
1.52	3/16" AR400 Sides/Ends/Tail gate in lieu of standard 7 ga grade 50	\$ 4,576
1.53	36" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 18,119
1.54	42" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 19,125
1.55	48" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 19,999
1.56	Top grate screens – Standard 3/8" rod x 3/8" rod	\$ 3,578
1.57	Top grate screens – Heavy Duty 3/8" rod thru 2" flat	\$ 4,793
1.58	Sloped Mild Steel side boards	\$ 1,643
1.59	Sloped 201SS Steel side boards	\$ 3,267
1.60	Underbody Pan – stainless steel	\$ 1,174
1.61	Rubber belt over chain conveyor	\$ 3,330
1.62	Double conveyor cross bars	\$ 1,441
1.63	Steel conveyor cover	\$ 1,858
1.64	Dual auger option (INCLUDES STANDARD TOP SCREENS ABOVE)	\$ 9,486

SEE "1.0 Box (Options) Page" for additional accessories & options

	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson Model Muni 2 15 Body
	List Truck Type Box Fits	Tandem Axle with 132" CT
	Box Style	Crossmemberless design with 22 degree sloping C19sides and live (conveyor) floor
	Width & Length of Box	15' long x 96" width
	Side Panel Description	36" high sides, grade 50, 65000 PSI, 1 piece sloping construction, 6" radius corners, dirt shedding boxed top rail and 4" board pockets
	Front Panel Description	10 gauge, grade 50, 65000 PSI steel
	Floor Description	28" main conveyor chain. 15" spreader apron, 1/4" AR400 conveyor floor. 8 tooth, 2" ID diameter sprockets driven by 25:1 planetary gear case driven by piston type drive motor. Stainless steel inner / outer longsills. Rear discharge with spinner assembly.
	Corner Post Description	5" x 12 3/4", 7 gauge full depth, tied to 12" steel rear apron with 1/4" plate steel tailgate latch reinforcements
	Under Structure Description	Stainless steel formed long sills with telescopic hoist
	Tailgate Description	7-gauge steel, grade 50 65000 PSI, boxed tailgate brace, sloping braces. 1 1/4" upper / lower pins
	Hinge Description	Upper hinges 1" thick flame cut
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting package rubber grommeted with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.
	Is Installation included in price?	Yes or No <u>X</u>
	Is Box Painted?	Yes or No <u>X</u>
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,605
	TOTAL PRICE:	\$ 33,441

Spec #	Description	Answer
	Box Options	
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson MuniBody	\$ 9,937
1.63	22 degree sloped option (No Charge)	\$ -
1.64	35 degree sloped option (No Charge)	\$ -
1.65	Munibody Flat Floor Upgrade, inc single side brace, AR floor (Mild Bodies) (No auger)	\$ 4,050
1.66	Munibody Flat Floor Upgrade, inc single side brace, AR floor (SS Bodies) (No Auger)	\$ 4,050
1.6	External Dog House option	\$ 2,343
1.7	Front cross conveyor and rear discharge (9-12) (SA pin to pin cylinder)	\$ 2,656
1.8	Front cross conveyor and rear discharge (13-16) (SA pin to pin cylinder)	\$ 2,656
1.9	Front "Center" and rear discharge 9'-12' bodies	\$ 412
1.10	Front "Center" and rear discharge 13'-17' bodies	\$ 3,836
1.11	Conveyor chain oiling system, installed	\$ 323
1.12	Fold up side ladder	\$ 843
1.13	Fold up side ladder, stainless steel	\$ 1,377
1.14	Polyurethane spinner disc in lieu of steel	\$ 233
1.15	Rear asphalt patching pan, with chute and mount (front/rear discharge)	\$ 850
1.16	Rear asphalt patching pan, mild steel (rear discharge only)	\$ 290
1.17	Rear spinner assembly with chute and mount	\$ 2,539
1.18	Front berm chute for right hand discharge, mild steel	\$ 235
1.19	Rear berm chute, mild steel	\$ 886
1.20	Fender mounted tool boxes on both sides – Mild Steel 13' and longer	\$ 3,073
1.21	Fender mounted tool boxes on both sides – Mild Steel 12' and shorter	\$ 2,789
1.22	Fender mounted tool box on CS or SS – Mild steel 13' and longer	\$ 1,702
1.23	Fender mounted tool box on CS or SS – Mild steel 12' and shorter	\$ 1,560
1.24	Fender mounted tool boxes on both sides – 13' and longer SS	\$ 4,983
1.25	Fender mounted tool boxes on both sides – 12' and shorter SS	\$ 4,035
1.26	Fender mounted tool box on CS or SS – 13' and longer SS	\$ 2,657
1.27	Fender mounted tool box on CS or SS – 12' and shorter SS	\$ 2,183
1.28	75 gallon poly prewet tank on both sides (22deg or 35deg muni)	\$ 2,438
1.29	75 gallon poly prewet tank on drivers side or passenger side (22deg or 35deg muni)	\$ 1,384
1.30	105 gallon poly prewet tank on both sides (22deg muni)	\$ 4,041
1.31	105 gallon poly prewet tank on drivers side or passenger side (22deg muni)	\$ 2,185
1.32	150 gallon poly prewet tank on both sides (22deg muni)	\$ 5,927
1.33	150 gallon poly prewet tank on drivers side or passenge side (22deg muni)	\$ 3,129
1.34	115 gallon poly prewet tank on both sides (35deg muni)	\$ 4,309
1.35	115 gallon poly prewet tank on drivers side or passenger side (35deg muni)	\$ 2,320
1.36	165 gallon poly prewet tank on both sides (35deg muni)	\$ 4,236
1.37	165 gallon poly prewet tank on drivers side or passenger side (35deg muni)	\$ 2,283
1.38	230 gallon poly prewet tank on both sides (35deg muni)	\$ 6,229
1.39	230 gallon poly prewet tank on drivers side or passenge side (35deg muni)	\$ 3,279
1.40	Cradle mount hydraulic reservoir (external dog house only)	\$ 709
1.41	Side mount oil reservoir (internal doghouse)	\$ 327
1.50	42" Steel Sides & Ends / 7 ga grade 50	\$ 454
1.51	48" Steel Sides & Ends / 7 ga grade 50	\$ 936
1.52	3/16" AR400 Sides/Ends/Tail gate in lieu of standard 7 ga grade 50	\$ 4,967
1.53	36" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 20,217
1.54	42" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 21,315
1.55	48" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$ 22,274
1.56	Top grate screens – Standard 3/8" rod x 3/8" rod	\$ 3,995
1.57	Top grate screens – Heavy Duty 3/8" rod thru 2" flat	\$ 5,347
1.58	Sloped Mild Steel side boards	\$ 1,800
1.59	Sloped 201SS Steel side boards	\$ 3,504
1.60	Underbody Pan – stainless steel	\$ 1,314
1.61	Rubber belt over chain conveyor	\$ 3,750
1.62	Double conveyor cross bars	\$ 1,638
1.63	Steel conveyor cover	\$ 1,948
1.64	Dual auger option (INCLUDES STANDARD TOP SCREENS ABOVE)	\$ 10,406

SEE "1.0 Box (Options) Page" for additional accessories & options

	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165

Price quote for:		1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co		
Contact Person:	Aaron Carlson		
Street Address:	9150 Pillsbury Ave. South		
P.O. Box:			
City, State, Zip:	Bloomington, MN 55420		
Phone #:	952-888-2525		
Toll Free #:	800-888-7671		
Fax #:	952-656-7159		
Email Address:	aaron.carlson@mgxequipment.com		
Item #	Information Requested	Answer	
1.0	Box Make and Model	Henderson Model Muni 2 16' Body	
	List Truck Type Box Fits	Tandem Axle with 144" CT	
	Box Style	Crossmemberless design with 22 degree sloping sides and live (conveyor) floor	
	Width & Length of Box	16' long x 96" width	
	Side Panel Description	36" high sides, grade 50, 65000 PSI, 1 piece sloping construction, 6" radius corners, dirt shedding boxed top rail and 4" board pockets	
	Front Panel Description	10 gauge, grade 50, 65000 PSI steel	
	Floor Description	28" main conveyor chain. 15" spreader apron, 1/4" AR400 conveyor floor. 8 tooth, 2" ID diameter sprockets driven by 25:1 planetary gear case driven by piston type drive motor. Stainless steel inner / outer longills. Rear discharge with spinner assembly.	
	Corner Post Description	5" x 12 3/4", 7 gauge full depth, tied to 12" steel rear apron with 1/4" plate steel tailgate latch reinforcements	
	Under Structure Description	Stainless steel formed long sills with telescopic hoist	
	Tailgate Description	7-gauge steel, grade 50 65000 PSI, boxed tailgate brace, sloping braces. 1 1/4" upper / lower pins	
	Hinge Description	Upper hinges 1" thick flame cut	
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting, package, rubber grommets with 1 piece sealed wiring harness. Stop, tail and turn in rear corner posts. Air tailgate trip as standard. Rear anti-sail mudflaps included.	
	Is Installation included in price?	Yes ___ or No <u>X</u>	
	Is Box Painted?	Yes ___ or No <u>X</u>	
	Warranty Information	1 year parts and labor	
	List Volume Discounts	10 + less 4%	
1.2	Cost for Painting box per spec	\$	4,675
		TOTAL PRICE:	\$ 34,948

1.3	Wiring Standoffs	\$	165
	Box Options		
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$	1,521
1.5	Installation Price of Henderson MuniBody	\$	9,937
1.63	22 degree sloped option (No Charge)	\$	-
1.64	35 degree sloped option (No Charge)	\$	-
1.65	Munibody Flat Floor Upgrade, inc single side brace, AR floor (Mild Bodies) (No auger)	\$	4,050
1.66	Munibody Flat Floor Upgrade, inc single side brace, AR floor (SS Bodies) (No Auger)	\$	4,050
1.6	External Dog House option	\$	2,343
1.7	Front cross conveyor and rear discharge (9-12) (SA pin to pin cylinder)	\$	2,656
1.8	Front cross conveyor and rear discharge (13-16) (SA pin to pin cylinder)	\$	2,656
1.9	Front "Center" and rear discharge 9'-12' bodies	\$	412
1.10	Front "Center" and rear discharge 13'-17' bodies	\$	3,836
1.11	Conveyor chain oiling system, installed	\$	323
1.12	Fold up side ladder	\$	843
1.13	Fold up side ladder, stainless steel	\$	1,377
1.14	Polyurethane spinner disc in lieu of steel	\$	233
1.15	Rear asphalt patching pan, with chute and mount (front/rear discharge)	\$	850
1.16	Rear asphalt patching pan, mild steel (rear discharge only)	\$	290
1.17	Rear spinner assembly with chute and mount	\$	2,539
1.18	Front berm chute for right hand discharge, mild steel	\$	235
1.19	Rear berm chute, mild steel	\$	886
1.20	Fender mounted tool boxes on both sides – Mild Steel 13' and longer	\$	3,073
1.21	Fender mounted tool boxes on both sides – Mild Steel 12' and shorter	\$	2,789
1.22	Fender mounted tool box on CS or SS – Mild steel 13' and longer	\$	1,702
1.23	Fender mounted tool box on CS or SS – Mild steel 12' and shorter	\$	1,560
1.24	Fender mounted tool boxes on both sides – 13' and longer SS	\$	4,983
1.25	Fender mounted tool boxes on both sides – 12' and shorter SS	\$	4,035
1.26	Fender mounted tool box on CS or SS – 13' and longer SS	\$	2,657
1.27	Fender mounted tool box on CS or SS – 12' and shorter SS	\$	2,183
1.28	75 gallon poly prewet tank on both sides (22deg or 35deg muni)	\$	2,438
1.29	75 gallon poly prewet tank on drivers side or passenger side (22deg or 35deg muni)	\$	1,384
1.30	105 gallon poly prewet tank on both sides (22deg muni)	\$	4,041
1.31	105 gallon poly prewet tank on drivers side or passenger side (22deg muni)	\$	2,185
1.32	150 gallon poly prewet tank on both sides (22deg muni)	\$	5,927
1.33	150 gallon poly prewet tank on drivers side or passenge side (22deg muni)	\$	3,129
1.34	115 gallon poly prewet tank on both sides (35deg muni)	\$	4,309
1.35	115 gallon poly prewet tank on drivers side or passenger side (35deg muni)	\$	2,320
1.36	165 gallon poly prewet tank on both sides (35deg muni)	\$	4,236
1.37	165 gallon poly prewet tank on drivers side or passenger side (35deg muni)	\$	2,283
1.38	230 gallon poly prewet tank on both sides (35deg muni)	\$	6,229
1.39	230 gallon poly prewet tank on drivers side or passenge side (35deg muni)	\$	3,279
1.40	Cradle mount hydraulic reservoir (external dog house only)	\$	709
1.41	Side mount oil reservoir (internal doghouse)	\$	327
1.50	42" Steel Sides & Ends / 7 ga grade 50	\$	465
1.51	48" Steel Sides & Ends / 7 ga grade 50	\$	959
1.52	3/16" AR400 Sides/Ends/Tail gate in lieu of standard 7 ga grade 50	\$	5,014
1.53	36" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$	21,505
1.54	42" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$	22,644
1.55	48" 201 SS Sides & Ends / 1/4" AR400 Conveyor Floor option	\$	23,645
1.56	Top grate screens – Standard 3/8" rod x 3/8" rod	\$	4,194
1.57	Top grate screens – Heavy Duty 3/8" rod thru 2" flat	\$	5,616
1.58	Sloped Mild Steel side boards	\$	1,884
1.59	Sloped 201SS Steel side boards	\$	3,705
1.60	Underbody Pan – stainless steel	\$	1,391
1.61	Rubber belt over chain conveyor	\$	3,997
1.62	Double conveyor cross bars	\$	1,762
1.63	Steel conveyor cover	\$	2,054

SEE "1.0 Box (Options) Page" for additional accessories & options

	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$	7
	Delivery Starting Point City, State, & Zip:		
	Bloomington, MN 55420		
	Body Shop Rate	\$	165
	Mechanic Shop Rate	\$	165

Price quote for:	1.0 Exhibit D PRICE SCHEDULE DUMP BOX	
Vendor Name:	Aspen Equipment Co	
Contact Person:	Aaron Carlson	
Street Address:	9150 Pillsbury Ave. South	
P.O. Box:		
City, State, Zip:	Bloomington, MN 55420	
Phone #:	952-888-2525	
Toll Free #:	800-888-7671	
Fax #:	952-656-7159	
Email Address:	aaron.carlson@mgxequipment.com	
Item #	Information Requested	Answer
1.0	Box Make and Model	Henderson 11' Blackbelt Maxx Conveyor Body
	List Truck Type Box Fits	Tandem Axle
	Box Style	Cross Memberless
	Width & Length of Box	11' long x 96" width
	Side Panel Description	46" sides, 3/16" AR400 steel, 1 piece with fully boxed debris shedding top rail, 71 degree slope, Two horizontal side braces
	Front Panel Description	3/16" AR400 steel
	Floor Description	1/4" AR400 steel with heat resistant UHMW floor liner
	Corner Post Description	Integrated rear cabinet assembly to house tailgate lift cylinders,, tailgate latch release cylinders, and, hydraulic manifold assembly
	Under Structure Description	Floor supported with 1/4"G50 formed floor angles.
	Tailgate Description	Full perimeter boxing, overcenter tailgate latches, high lift tailgate
	Hinge Description	
	Description of Peripheral Items (Lights, Access Steps, etc.)	FMVSS 108 standard LED lighting, package, 54" wide conveyor belt LSBT "Load Sense Belt Tensioning" system
	Is Installation included in price?	Yes or No X
	Is Box Painted?	Yes or No X
	Warranty Information	1 year parts and labor
	List Volume Discounts	10 + less 4%
1.2	Cost for Painting box per spec	\$ 4,950
	TOTAL PRICE:	\$ 69,473

Spec #	Description	Answer
1.3	Wiring Standoffs	\$ 165
1.4	Box Vibrator - Cougar Model DC3200 (Standard Application)	\$ 1,521
1.5	Installation Price of Henderson Blackbelt Maxx	\$ 10,778
1.50	Add for 12' Blackbelt Maxx, AR400 construction (Requires paint)	\$ 760
1.51	Add for 13' Blackbelt Maxx, AR400 construction (Requires paint)	\$ 1,507
1.52	Add for 14' Blackbelt Maxx, AR400 construction (Requires paint)	\$ 2,249
1.53	Add for 15' Blackbelt Maxx, AR400 construction (Requires paint)	\$ 6,108
1.54	Add for 16' Blackbelt Maxx, AR400 construction (Requires paint)	\$ 9,955
1.55	Add for 17' Blackbelt Maxx, AR400 construction (Requires paint)	\$ 13,819
1.56	Add for 11' Blackbelt Maxx, 201ss construction	\$ 4,203
1.57	Add for 12' Blackbelt Maxx, 201ss construction	\$ 4,990
1.58	Add for 13' Blackbelt Maxx, 201ss construction	\$ 5,761
1.59	Add for 14' Blackbelt Maxx, 201ss construction	\$ 6,525
1.60	Add for 15' Blackbelt Maxx, 201ss construction	\$ 10,406
1.61	Add for 16' Blackbelt Maxx, 201ss construction	\$ 14,277
1.62	Add for 17' Blackbelt Maxx, 201ss construction	\$ 18,156
1.63	Winter Tailgate w/ SS basic spinner	\$ 13,913
1.64	Winter Tailgate w/ Dcast, Henderson Cntrl	\$ 23,374
1.65	Berm Chute for Winter Tailgate	\$ 1,665
1.66	DUAL 155(gal) liquid tanks for 11' BBMAXX (201ss)	\$ 6,971
1.67	DUAL 182(gal) liquid tanks for 12' BBMAXX (201ss)	\$ 7,249
1.68	DUAL 210(gal) liquid tanks for 13' BBMAXX (201ss)	\$ 8,172
1.69	DUAL 237(gal) liquid tanks for 14' BBMAXX (201ss)	\$ 8,397
1.70	DUAL 265(gal) liquid tanks for 15' BBMAXX (201ss)	\$ 8,626
1.71	DUAL 292(gal) liquid tanks for 16' BBMAXX (201ss)	\$ 8,819
1.72	DUAL 320(gal) liquid tanks for 17' BBMAXX (201ss)	\$ 9,036
1.73	Single Lane Anti-Ice Kit (req's liquid tanks)	\$ 6,028
1.74	Three Lane Anti-Ice Kit (req's liquid tanks)	\$ 9,068
1.75	Prewet Slurry Kit (req's liquid tanks)	\$ 4,025

SEE "1.0 Box (Options) Page" for additional accessories & options

	Cost per loaded mile for pickup and or delivery of vehicle (if applicable):	\$ 7
	Delivery Starting Point City, State, & Zip:	
	Bloomington, MN 55420	
	Body Shop Rate	\$ 165
	Mechanic Shop Rate	\$ 165